


PROBE MOUNTING



NOTES: THE TEMPERATURE SENSOR MOUNTING SHOULD BE IN A PLACE THAT IS FREE OF EXHAUST GASES OR COWL FLAPS AIRFLOW, THE IDEAL PLACE IS TWO FEET OUT FROM THE WING ROOT ON THE BOTTOM OF THE WING. SENSOR LEADS MAY BE LENGTHENED OR SHORTENED WITHOUT AFFECTING CALIBRATION.

REVISIONS		
NO	DATE	BY
1	9/14/09	RGW
2		
3		
4		
5		

DRWN BY RW	SCALE NONE	MATERIAL
CHK'D	DATE 2/27/07	DRAWING NO.
TRACED	APP'D RGW	303-018

D307PS OUTLINE

DAVTRON INC.
427 HILLCREST WAY
REDWOOD CITY, CA 94062